



US Army Corps  
of Engineers®

Detroit District  
P.O. Box 1027  
Detroit, MI 48231-1027  
(313) 226-6796  
FAX - (313) 226-3519

# Notice to Navigation Interests

---

Notice No. L02-55

Date: 27 AUGUST 2002

---

Waterway: LAKE MICHIGAN

Location: WISCONSIN

---

CELRE-OT-T

CONDITION OF FEDERAL NAVIGATION CHANNEL  
PORT WASHINGTON HARBOR

1. Condition surveys performed within the Federal navigation channel at the Port Washington Harbor, Wisconsin during June 2002, indicate shoaling as shown on the back of this sheet.
2. Mariners are urged to use extreme caution in the area.
3. All inquiries should be addressed to CELRE-OT-T and should refer to Notice to Navigation Interests No. L02-55. Internet address: <http://huron.lre.usace.army.mil/OandM/o&m.html>


THOMAS H. MAGNESS  
Lieutenant Colonel, U.S. Army  
District Engineer

Notice to the Postmaster:

It is requested that the above notice be conspicuously and continuously posted until November 30, 2002.

Soundings are in Feet and are referred to Low Water Datum 576.8 Ft. above Mean Water Level at Father Point, Quebec, IGLD, 1955.

Shoals indicate least available depth below I.G.L.D.



Surveys taken: JUNE 2002

The information depicted on this map represents the results of surveys made on the date indicated and can only be considered as indicating the general conditions existing at that time.

PORT WASHINGTON HARBOR  
WISCONSIN

CONDITION OF CHANNEL

ISSUED: 27 AUGUST 2002

U.S. Army Engineer District, Detroit